





NORDAC FLEX SK 2x0E

QUICK-START




- (DE) Dieses Dokument ersetzt nicht die Originalanleitung. Lesen und beachten Sie die Sicherheitshinweise.
- (EN) This document does not replace the original instructions. Read and observe the safety information.
- (FR) Ce document ne remplace pas la notice d'origine. Lisez et respectez les consignes de sécurité.
- (ES) El presente documento no sustituye el manual original. Lea y cumpla las indicaciones de seguridad.
- (SE) Dokumentet ersätter inte originalbruksanvisningen. Läs och följ säkerhetsanvisningarna.
- (NL) Dit document is geen vervanging voor de originele handleiding. Lees dus de veiligheidsaanwijzingen en volg ze op.
- (PL) Niniejszy dokument nie zastępuje oryginalnej instrukcji. Przeczytać zasady bezpieczeństwa ostrzegawcze i ich przestrzegać.
- (RU) Этот документ не является заменой оригинальному руководству. Прочитайте и соблюдайте указания по технике безопасности.
- (CZ) Tento dokument nenahrazuje originální návod. Přečtěte si a respektujte bezpečnostní upozornění.
- (IT) Il presente documento non sostituisce le Istruzioni per l'uso originali. Leggere e rispettare le indicazioni di sicurezza.
- (DK) Dette dokument er ingen erstatning for originalvejledningen. Du bedes læse og følge sikkerhedsanvisningerne.
- (FI) Tämä asiakirja ei korvaa alkuperäistä käyttöohjetta. Lue turvallisuusohjeet sekä noudata niitä.
- (BR) Este documento não substitui o manual original. Leia e observe os avisos de segurança.
- (CN) 这份文档不能替代原版使用说明书。需阅读和注意安全须知和警告提示。
- (TR) Bu doküman orijinal kılavuzun yerine geçmez. Güvenlik bilgilerini okuyun ve dikkate alın.


NORDAC FLEX SK 2x0E



1A




*) SK CU4-...



SK 2x0E - xxx - 3xx - ...

3~


L1
L2
L3




SK 2x0E - xxx - 1xx - ...

1~


L1
N



1B




*) SK CU4-...



SK 2x0E - xxx - 3xx - ...

3~


L1
L2
L3




SK 2x0E - xxx - 1xx - ...

1~

L1
N



1C




NORDAC FLEX SK 2x0E



SK PAR-3H



SK CSX-3H



NORDCON



P102		[2.0]	[s]	
P103		[2.0]	[s]	
P104	f_{min}	[0.0]	[Hz]	
P105	f_{max}	[50]	[Hz]	
1A	P400 [-01]	\rightarrow	[1]	
	P420 [-01]		[1]	
	P420 [-02]		[2]	
	P420 [-03]	min. f_1 max. f_1	[4]	
	P465 [-01]	f_1	[5.0]	[Hz]
				1B



www.nord.com